



**Trade &  
Investment  
Mine Safety**

File No.: 11/3219

Mine Manager  
Tahmoor Colliery  
PO Box 100  
TAHMOOR NSW 2573

Dear Sir,


**Re: Tahmoor Colliery Longwall Panel 27 – Variations to Subsidence Monitoring Programme**

I refer to Tahmoor Colliery's proposed variations to the subsidence monitoring programme for Longwall Panel 27, as outlined within a letter from Community Coordinator, Tahmoor Colliery entitled "Cessation of Monitoring for Longwall 27" dated 4 April 2014.

Pursuant to Condition 12 of Director General's approval of SMP for Longwalls 27 - 30 (File No. 11/3219, dated 31 October 2012), I approve the subsidence monitoring variations proposed in the letter noted above, subject to the following condition:

- 1 The leaseholder must comply with the monitoring/inspection requirements of Office of National Rail Safety Regulator and the owners/operators of infrastructure that may be affected by subsidence arising from extraction of the subject longwall panel.

Yours faithfully,



Dr Gang  
Principal Subsidence Engineer

2 May 2014