



SIMEC Mining:

## **Tahmoor South Longwalls S1A to S6A**

Subsidence Management Plan for potential impacts to No. 3030 Remembrance Drive, Bargo

## AUTHORISATION OF MANAGEMENT PLAN

### Authorised on behalf of Tahmoor Coal:

Name: Zina Ainsworth

Signature: *Zina Ainsworth*

Position: Environment and Community Manager

Date: 10th Feb 2023

### Authorised on behalf of the land owner of No. 3030 Remembrance Drive, Tahmoor:

Name: Kevin Hawach

Signature:

Position: Land owner

Date:

### Authorised on behalf of Bargo Petroleum lessee:

Name: Rahat Iqbal

Signature:

Position: Bargo Petroleum

Date:

**DOCUMENT REGISTER**

<b>Date</b>	<b>Report No.</b>	<b>Rev</b>	<b>Comments</b>
Feb-23	MSEC1193-13	A	First draft

References:-

AS/NZS ISO 31000:2009 Risk Management – Principles and guidelines

AEC (2022) *Groundwater Monitoring Event (GME) Report, Bargo Petroleum Service Station, Aurora Environmental Consulting, 9 December 2022.*

JMA (2022) *Pre-Mining Inspection Report No. R0784, 3030 Remembrance Driveway, JMA Solutions, May 2022.*

JMA (2022) *Hazard Identification Report: 3030 Remembrance Driveway, Bargo, JMA Solutions, 20220810-R1, August 2022.*

MSIA (2022a) *Workplace Inspection to identify increased risk from Tahmoor Mine Mining Induced Subsidence for Bargo Petroleum, Mine Safety Institute of Australia, 5 August 2022.*

MSIA (2022b) *Workplace Inspection to identify increased risk from Tahmoor Mine Mining Induced Subsidence for Frapen Motorsports, Automotive Repairs, Mine Safety Institute of Australia, 5 August 2022.*

MSIA (2022c) *Workplace Inspection to identify increased risk from Tahmoor Mine Mining Induced Subsidence for Road Tested Spares, Auto Wreckers, Mine Safety Institute of Australia, 4 August 2022.*

MSO (2017) *Managing risks of subsidence – Guide | WHS (Mines and Petroleum Sites) Legislation, NSW Department of Planning & Environment, Resources Regulator, Mine Safety Operations, February 2017.*

MSEC (2022) *Tahmoor South- Longwalls S1A to S6A - Subsidence ground movement predictions and subsidence impact assessments for natural features and surface infrastructure in support of the Extraction Plan Application. (Report No. MSEC1192, Revision A, May 2022), prepared by Mine Subsidence Engineering Consultants.*

Tahmoor Coal (2022) *Risk Assessment Report – Bargo Petroleum. Tahmoor South, November 2022.*

Tanknology (2022) *Bargo Petroleum, 3030 Remembrance Drive, Tahmoor, Report No. SO32493, 14 January 2023.*



This information has been  
retracted  
- For more information  
contact Tahmoor Coal

---

**SIMEC**

Level 28, 88 Phillip Street,  
Sydney NSW 2000

Legal entity name goes here ABN: 00 000 000 000

**T:** +61 (0) 2 0000 0000

**E:** xxxxxxxx.xxxxxxx@simecgg.com

**simec.com**

MEMBER OF

