



SIMEC

Tahmoor Coal Pty Ltd

STONEQUARRY CREEK ROCKBAR

MANAGEMENT PLAN

**Tahmoor North - Western Domain
Longwalls West 3 and West 4**

September 2021

simecfg.com

This page has been left blank
intentionally.

Document Control

APPLICANT: Tahmoor Coal Pty Ltd
MINE: Tahmoor Coal Mine
DEVELOPMENT APPROVAL: DA 57/93 (as modified) and DA 67/98 (as modified)
MINING LEASES: ML 1376 and ML 1539
DOCUMENT TITLE: Tahmoor North - Western Domain
Longwalls West 3 and West 4
Stonequarry Creek Rockbar Management Plan
DOCUMENT NUMBER: TAH-HSEC-352
PUBLICATION DATE: September 2021
DOCUMENT STATUS: Final (Version 7)
PREPARED BY: April Hudson
Approvals Specialist
Tahmoor Coal – SIMEC Mining
APPROVED BY: Zina Ainsworth
Environment and Community Manager
Tahmoor Coal – SIMEC Mining

Signature: 
Date: 13.9.21

Malcolm Waterfall
Mining Engineering Manager
Tahmoor Coal – SIMEC Mining

Signature: 
Date: 13.9.21

Peter Vale
Head of Coal Mines
Tahmoor Coal – SIMEC Mining

Signature: 
Date: 13.9.21

This page has been left blank
intentionally.

Table of Contents

Table of Contents	5
List of Figures	6
List of Tables	7
1 Introduction	8
1.1 Background	8
1.2 Scope	9
2 Regulatory Requirements	11
2.1 Project Approval.....	11
2.1.1 Development Consent	11
2.2 Relevant Legislation	13
2.3 Consultation	13
3 Existing Environment.....	14
3.1 Stonequarry Creek Rockbar SR17	14
3.2 Grinding Groove Site	16
4 Adaptive Management Strategy	19
5 Predicted Subsidence Impacts and Environmental Consequences	20
5.1 Observed and Predicted Subsidence Movements across Stonequarry Creek including at Rockbar SR17	20
5.1.1 Valley closure	20
5.1.2 Conventional subsidence movements	21
5.2 Observations at Rockbar SR17 and Aboriginal Heritage Site.....	23
5.3 Monitoring Results from Other Grinding Groove Sites	23
5.4 Predicted Environmental Consequences	23
5.5 Management strategy.....	25
5.6 Development of subsidence and valley closure movements during the mining of LW W3....	26
5.6.1 Initial subsidence at commencement of LW W3	26
5.6.2 Development of valley closure of LW W3.....	27
6 Subsidence Monitoring Program.....	28
6.1 Performance Measures and Indicators.....	28
6.2 Subsidence Monitoring Program	30
6.2.1 Primary Monitoring Activities	30
6.2.2 Key Monitoring Systems	31
6.2.3 Secondary Monitoring Activities.....	33
6.3 Baseline Monitoring for Future Extraction Plans.....	41
7 Subsidence Management Strategies	42
7.1 Trigger Action Response Plan	42
7.1.1 Key Assessment Criteria.....	43
7.2 Reporting of results.....	43

7.3	Contingency Plan.....	44
7.4	Governance Structure	45
7.4.1	Steering Committee	45
7.4.2	Technical Committee	45
8	Review and Improvement	46
8.1	Reporting Requirements	46
8.2	Review and Auditing	46
8.3	Roles and Responsibilities.....	47
9	Document Information	48
9.1	References.....	48
9.2	Abbreviations	48
9.3	Glossary of Terms.....	49
9.4	Change Information	50
Appendix A – Trigger Action Response Plan	51	
Appendix B – Monitoring Drawings	55	
Appendix C – Representative Aboriginal Party Consultation.....	56	
Appendix D – Subsidence Advice for Heritage Items (Niche, 2021)	57	

List of Figures

Figure 1-1	Location of Stonequarry Creek Rockbar SR17 and AHIMS site #52-2-2068 (EMM, 2021)	10
Figure 3-1	Stonequarry Creek and Pool SR17 (Pool SR17 in blue; Rockbar SR17 in red)	15
Figure 3-2	Key Existing Fractures in Rockbar SR17 (SCT, 2021).....	15
Figure 3-3	Geological section exposed in bank downstream of SR17 (SCT, 2021)	16
Figure 3-4	Stonequarry Creek Rockbar 17 – Groupings of Grinding Grooves A, B and C (EMM, 2021)	17
Figure 3-5	Grinding Groove – Group A (EMM, 2021)	17
Figure 3-6	General Photos of the site.....	18
Figure 5-1	Total Closure following Extraction of LW W1-W2 (MSEC, 2021)	20
Figure 5-2	Predicted conventional subsidence profiles between LW W3 and Rockbar SR17 (MSEC, 2021)22	
Figure 5-3	Experience of relationship between impacts and closure in the context of the existing condition of SR17 (SCT, 2021a)	24
Figure 5-4	Observed development of initial subsidence above LW W2 relative to length of extraction	26
Figure 5-5	Observed development of closure across Stonequarry Creek during the mining of LW W2 relative to time and length of extraction.....	27
Figure 6-1	Overview of Survey Monitoring surrounding Stonequarry Creek	38
Figure 6-2	Overview of High-Resolution Survey Monitoring	38
Figure 6-3	Overview of Water Monitoring Locations.....	39
Figure 6-4	Inclinometer location (purple dot) same location for Stress Cell Monitoring.	40

List of Tables

Table 2-1	Key Conditions from DA 67/98 regarding AHIMS site #52-2-2068.....	11
Table 6-1	Subsidence Performance Measures and Performance Indicators for AHIMS Site	
#52-2-2068	29	
Table 6-2	Monitoring Program for the Rockbar SR17 and AHIMS Site #52-2-2068	34
Table 7-1	Monitoring Data Review and Reporting	43
Table 7-2	Framework of Remediation Options.....	44
Table 8-1	Members of the Stonequarry Creek Rockbar Steering Committee and Technical Committee	
	47	
Table 9-1	Abbreviations	48
Table 9-2	Document History.....	50



This information has been
retracted

- For more information
contact Tahmoor Coal

SIMEC

Level 28, 88 Phillip Street,
Sydney NSW 2000
Legal entity name goes here ABN: 00 000 000 000

T: +61 (0) 2 0000 0000
E: xxxxxxxx.xxxxxxx@simecfg.com
simec.com

MEMBER OF

